



April 21, 2017

Page 1 of 1

***External Notice: NovAtel Announces End of Life
for Multiple OEM6® Receiver Boards***

NovAtel Inc. is announcing the End of Life of the:

OEM615, OEM617, and OEM628 series boards (see discontinued part numbers below)

These products will be available for order until:

September 29, 2017 (or until inventory is depleted)

Shipments may be scheduled for no later than:

March 30, 2018

NovAtel will continue to support and repair these products until:

September 30, 2020

For a complete list of affected part numbers and the associated replacement part numbers, please refer to the table below:

| Discontinued Part Number | Replacement Part Number |
|---------------------------------|--------------------------------|
| OEM615-xxx-xxx-xxx | OEM719- |
| OEM615A-xxx-xxx-xxx | OEM719A- |
| OEM615B-xxx-xxx-xxx | OEM719B- |
| OEM615C-xxx-xxx-xxx | OEM719C- |
| OEM615V-xxx-xxx-xxx | OEM719- |
| OEM617-xxx-xxx-xxx | OEM719- |
| OEM617B-xxx-xxx-xxx | OEM719B- |
| OEM628-xxx-xxx-xxx | OEM729- |
| OEM628C-xxx-xxx-xxx | OEM729C- |
| OEM628E-xxx-xxx-xxx | OEM729- |
| OEM628V-xxx-xxx-xxx | OEM729- |

Notes:

- OEM617D, OEM625, and OEM638 series boards are not covered by this EOL document and continue to be available until further notice
- Software models between OEM6 and OEM7® are defined differently. For information on the OEM7 series receivers, please visit the NovAtel website:
<http://www.novatel.com/products/gnss-receivers/oem-receiver-boards/oem7-receivers/>